



# Drawing 1

REAR




FRONT

# Drawing 2



FRONT



# Drawing 3



FRONT


# Drawing 4

Mount the power switch with solder lugs toward the chassis opening.




# Drawing 5

FRONT







Drawing 7

